U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SECTION I						
MANUFACTURER'S NAME	EMERGENCY TELEPHONE NO.					
Oxy Metal Industries Corporation	(313) 497-9100					
ADDRESS (Number, Street, City, State, and ZIP Code) 21441 Hoover Road Warren, Michigan 48089						
CHEMICAL NAME AND SYNGNYMS Udylite Oxyfin TM #984		NAME AND SYNONYMS r Aid, Fine				
CHEMICAL FAMILY See Below	FORMULA See Below					

SECTION	V II -	HAZAF	RDOUS INGREDIENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS	x	Х	BASE METAL	x	Х
CATALYST	X	Х	ALLOYS	X	_X
VEHICLE	x	Х	METALLIC COATINGS	Х	Х
SOLVENTS '	X	X	FILLER METAL PLUS COATING OR CORE FLUX	x_	X
ADDITIVES	X	Х	OTHERS	X	<u> X</u>
OTHERS	x	Х		X	X
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES					
A finely divided powder consisting of a natural carbohydrate polymer.					Х
				X	Х
	_			x	Х
				X	Х

, 1	SECTION III - F	PHYSICAL DATA		•
BOILING POINT (°F.)	NA	SPECIFIC GRAVITY (H2O=1))	1.0
VAPOR PRESSURE (mm Hg.)	NA	PERCENT, VOLATILE BY VOLUME (%)	1 ,.1	None
VAPOR DENSITY (AIR=1)	NA	EVAPORATION RATE (=1)		None
SOLUBILITY IN WATER	Insoluble			_x
APPEARANCE AND ODOR W	hite odorless sol	lids.		

SECTION IV - FIRE	AND EXPLOSION HAZARD DAT	ΓΑ	
FLASH POINT (Method used) None	FLAMMABLE LIMITS None	Lel X	Uel X
EXTINGUISHING MEDIA CO2, Dry Chemical; or inert chemical	al foam.		
SPECIAL FIRE FIGHTING PROCEDURES None	. •		
	+ 1		
unusual fire and explosion hazards Product could contribute to the initia	ation of an expolsion by rea	son of its	
spontaneous heating and combustibl			

	<u> </u>						
			CTION	V	- HEAL	TH HAZARD D	ATA
THRESHOLD LIMIT Estimated as THICTS OF OVER Does not ap	s nus exposi	ance parti	iculate	e:_	30 mp	ocf	
EMERGENCY AND Does not ap	rinst /	AID PROCEDU	RES	· · · · · · ·			
Boes not up	<u> </u>						
	· · · · · ·		SECTIO	י מכ	VI - RE	ACTIVITY DAT	ſ A
STABILITY	UNS	TABLE	<u></u>	_		S TO AVOID	
	STA	STABLE X					
INCOMPATABILITY	(Mater	ials to avoid)		es	not ap	oly.	
HAZARDOUS DECO	MPO51	TION PRODUC			· · · · · · · · · · · · · · · · · · ·		
		MAY OCCUR				CONDITIONS TO A	VOID
HAZARDOUS POLYMERIZATION		WILL NOT O	CCUR	•	Х	·	
		1			Doe	s not apply.	
•		•				OR LEAK PROC	EDURES
STEPS TO BE TAK Sweep up an	en in o	urn to con	al is re itainei	LEA.	sed or s If wet	PILLED , shovel up ar	nd place in closed steel
cans.						ere ye.	
					-		
waste disposal Incinerate.	METHO	סכ					
						:	
				200		DOTTOTION IN	CORMATION
				SPE	ECIAL P	ROTECTION IN	FORWATION
RESPIRATORY PROTECTION (Specify type) A dust type respirator for chronic exposure above TLV Limit TLOCAL EXHAUST TLOCAL EXHAUST TABLE TAB							imit
VENTILATION NO NO				No -			
MECHANICAL (General) Sufficient to keep be			be			OTHER NO	
PROTECTIVE GLOVES EYE PROTECTION NO NO							
other protective equipment No							
	<u> </u>	SI	ECTIO	N I>	K - SPE	CIAL PRECAUT	IONS
PRECAUTIONS TO Keep dry. I	BE TA	KEN IN HAND	LING AN	on on	TORING groun	d. Permit goo	od air circulation. May
ignite spont	aneo						ant, closely confined area.
OTHER PRECAUTIONS							

PAGE (2)

Form OSHA-20 Rev. May 72